


HighRO 400 TSH


Elmas parmak freze ,Solid carbide endmills



SIPARIS NO,ORDER NO.	D	R	I	N	d1	d	L	Z
HighRO-400 3,0 R1,0 TSH	3	1	3	12	2,85	6	55	4
HighRO-400 4,0 R1,0 TSH	4	1	3	12	3,85	6	55	4
HighRO-400 5,0 R1,0 TSH	5	1	3	22	4,75	6	55	4
HighRO-400 6,0 R1,0 TSH	6	1	3	24	5	6	55	4
HighRO-400 8,0 R1,0 TSH	8	1	4	24	7	8	60	4
HighRO-400 10,0 R1,0 TSH	10	1	5	35	9	10	73	4
HighRO-400 12,0 R1,0 TSH	12	1	6	40	11	12	75	4

HighRO 400 L TSH

Uzun Elmas parmak freze ,Solid carbide endmills long series



SIPARIS NO, ORDER NO.	D	R	I	N	d1	d	L	Z
HighRO-400 L- 3,0 R1,0 TSH	3	1	3	17	2,5	6	75	4
HighRO-400 L- 4,0 R1,0 TSH	4	1	3	17	3,5	6	75	4
HighRO-400 L- 5,0 R1,0 TSH	5	1	3	19	4,5	6	75	4
HighRO-400 L- 6,0 R1,0 TSH	6	1	3	30	5	6	75	4
HighRO-400 L- 8,0 R1,0 TSH	8	1	4	30	7	8	100	4
HighRO-400 L-10,0 R1,0 TSH	10	1	5	40	9	10	100	4
HighRO-400 L-12,0 R1,0 TSH	12	1	6	40	11	12	100	4