

SharpRO-430 TSH

Elmas parmak freze ,Solid carbide endmills



MICRO
GRAIN


SHARP

TIALNX

60 HRC

Tolerans D
- 0,015
- 0,020

Z - 4



SIPARIS KODU, ORDER NO	D	l	d	L	Z
SharpRO-430- 3,0 TSH	3	9	3	50	4
SharpRO-430- 4,0 TSH	4	11	4	50	4
SharpRO-430- 5,0 TSH	5	13	5	50	4
SharpRO-430- 6,0 TSH	6	15	6	55	4
SharpRO-430- 7,0 TSH	7	18	7	55	4
SharpRO-430- 8,0 TSH	8	20	8	60	4
SharpRO-430- 9,0 TSH	9	22	9	60	4
SharpRO-430- 10 TSH	10	22	10	73	4
SharpRO-430- 12 TSH	12	26	12	75	4
SharpRO-430- 13 TSH	13	26	13	75	4
SharpRO-430- 14 TSH	14	30	14	83	4
SharpRO-430- 16 TSH	16	36	16	93	4
SharpRO-430- 18 TSH	18	40	18	93	4
SharpRO-430- 20 TSH	20	45	20	100	4

SharpRO-430L TSH

UZ

Uzun Elmas parmak freze ,Solid carbide endmills long series



SIPARIS KODU, ORDER NO	D	l	d	L	Z
SharpRO-430L- 3 TSH	3	10	3	75	4
SharpRO-430L- 4 TSH	4	15	4	75	4
SharpRO-430L- 5 TSH	5	20	5	75	4
SharpRO-430L- 6 TSH	6	40	6	100	4
SharpRO-430L- 7 TSH	7	40	7	100	4
SharpRO-430L- 8 TSH	8	40	8	100	4
SharpRO-430L- 9 TSH	9	40	9	100	4
SharpRO-430L-10 TSH	10	45	10	100	4
SharpRO-430L-12 TSH	12	45	12	100	4
SharpRO-430L-13 TSH	13	45	13	100	4
SharpRO-430L-14 TSH	14	55	14	150	4
SharpRO-430L-16 TSH	16	75	16	150	4
SharpRO-430L-18 TSH	18	75	18	150	4
SharpRO-430L-20 TSH	20	75	20	150	4