



SIPARIS NO,ORDER NO.	D	R	L	d	L	Z
HardCO-420RL- 3,0 R0,5 TX	3	0,5	12	3	75	4
HardCO-420RL- 4,0 R0,5 TX	4	0,5	14	4	75	4
HardCO-420RL- 5,0 R0,5 TX	5	0,5	15	5	75	4
HardCO-420RL- 6*75 R0,5 TX	6	0,5	16	6	75	4
HardCO-420RL- 6,0 R0,5 TX	6	0,5	16	6	100	4
HardCO-420RL- 8*75 R0,5 TX	8	0,5	20	8	75	4
HardCO-420RL- 8,0 R0,5 TX	8	0,5	20	8	100	4
HardCO-420RL-10,0 R0,5 TX	10	0,5	23	10	100	4
HardCO-420RL-12,0 R0,5 TX	12	0,5	26	12	100	4
HardCO-420RL- 3,0 R1,0 TX	3	1,00	12	3	75	4
HardCO-420RL- 4,0 R1,0 TX	4	1,00	14	4	75	4
HardCO-420RL- 5,0 R1,0 TX	5	1,00	15	5	75	4
HardCO-420RL- 6*75 R1,0 TX	6	1,00	16	6	75	4
HardCO-420RL- 6,0 R1,0 TX	6	1,00	16	6	100	4
HardCO-420RL- 8*75 R1,0 TX	8	1,00	20	8	75	4
HardCO-420RL- 8,0 R1,0 TX	8	1,00	20	8	100	4
HardCO-420RL-10,0 R1,0 TX	10	1,00	23	10	100	4
HardCO-420RL-12,0 R1,0 TX	12	1,00	26	12	100	4
HardCO-420RL- 6,0 R1,5 TX	6	1,50	16	6	100	4
HardCO-420RL- 8,0 R1,5 TX	8	1,50	20	8	100	4
HardRO-420RL-10,0 R2,0 TX	10	2,00	23	10	100	4
HardRO-420RL-12,0 R3,0 TX	12	3,00	26	12	100	4